

complications, as the one reported in our experience, mainly due to an incorrect surgical procedure.

To minimize the failure rates, a thorough selection of patients and the availability of disposable sets for VP insertion are mandatory.

References

- 1.